

Profile



©2000 National Coatings Corporation.
All Rights Reserved. CH-AP-002 06-01

SYSCO

Size: 70,000 Square Feet

Location: Walnut, California

Challenge *Sun-Damaged BUR Capsheet*

- Sun-damaged and leaking BUR capsheet.
- R-value efficiency loss resulting from hot capsheet.
- Budget constraints.

Solution *AcryPly® Restoration System*

- Reinforced seamless system.
- Phased installation.
- 50°F cooler peak roof surface temperatures.
- Improved energy efficiency.

With their new Cool Roof System, Sysco has overlaid a failing roof with additional high strength waterproofing and improved their building's insulating efficiency.



(800)423-9557, www.nationalcoatings.com